



Figure 6

An unterminated LVTTTL line yields excessive ringing due to impedance mismatches.