



Figure 2 Performing a USB transaction over a wireless link requires that intermediate subsystems work to prevent the USB turnaround timer from creating problems (courtesy Icron Technologies).