

TABLE B PRODUCTS' RELEVANT VERSION INFORMATION

Product	Hardware/software revision and other configuration details
Apple MacBook	GbE (Marvell Yukon 88E8085): driver version 10.12.7.3; Wi-Fi (Broadcom 802.11n): driver version 4.80.75.0
Dell PowerEdge 400SC	GbE (Intel Pro/1000 MT): driver version 8.9.10
Linksys RV042 router	Firmware version 1.3.8.2
Aztech Systems HL105E	Firmware version 1.6
Linksys PLE200	Firmware version INT6000-MAC-1-4-1454-650-20070226-SP2-B
Netgear HDX101	Firmware version spirit_dh10p_9010_v2 s2_2_5_cvs
Netgear XE102	Firmware version unknown
Panasonic BL-PA100	Firmware version unknown
Apple Airport Extreme N router and access point	Firmware version 7.1.1
Belkin F5D6130 access point	Firmware version 1.89.0025-Patch, boot version 1.81.28-Patch, hardware version 01A
Belkin F5D7130 access point	Firmware version 4.03.03, boot version 1.03.08, hardware version F5D7230; this is a Belkin router with access-point-only firmware
Buffalo Technology Wireless-N Nfiniti dual-band gigabit router and access point	Version 1.46 (1.08-UNKNOWN), "High Throughput Mode" enabled (disabling slightly worsened transfer rates), set to A-MSDU aggregation
Intel Pro/Wireless 5000 access point	Firmware version 1.3-18.5

Note: All software was up-to-date as of the testing.