



Figure 7 The two small wires in Figure 6 cause these dips in impedance. Using a 9-sec pulse generator causes the top trace, and the scope's internal pulse generator causes the bottom trace (courtesy Picosecond Pulse Labs).
