



Figure A The CT-1/HP-461A combination clearly displays a 100- μ A pulse train (a). The noise floor causes the slight trace thickening. The P6022/Preamble 1855 presentation shows degraded signal-to-noise performance (b).