



Figure 4 The steep rise and reverse overshoot in Figure 3's circuit are artifacts of sense-resistor parasitic inductance.