



Figure 1

This hysteretic regulator suffers from unpredictability of the switching frequency because of C_{OUT} ESR variance.