



**Figure 2** Modified pads provide isolated Kelvin connections that eliminate errors introduced by voltage drops across soldered connections carrying high current.