



Figure B Introducing a 3-in., noncoaxial ground connection causes pronounced signal distortion and postevent ringing.
