



Figure 14 This waveform has the same conditions as Figure 13, except with increased noise bandwidth of 5 MHz, exceeding the regulator's bandwidth and resulting in 50-mV-p-p output error.

---