



Figure 26 The P30 embedded-memory voltage regulator must maintain a $\pm 0.1V$ error band. Control-line movement causes 50-mA load steps, necessitating attention to C_{OUT} selection.