



Figure 19 An abrupt change in the reference (Trace A) causes an amplitude-level-control response (Trace B). IC_5 's compensation capacitor sets the settling time. This capacitor must be large enough to stabilize the loop at the lowest expected signal-input frequency.
