



Figure 1 Gain error causes the transfer function of an ADC to rotate around the digital-input code of zero.