



**Figure 9** The resonant Royer collector waveshape is identical to that of the LT3401 circuit in Figure 5 (Trace A). The controlled transition times of the LT1534 current sink attenuate the high-frequency harmonics (Trace B).

---