



Figure 1 Off-chip factors limit the ability to measure a high-speed serial link's performance, as the insertion loss across 34 in. of FR4 PCB indicates. This loss curve was measured using a pulse-response technique that produces results similar to those you can obtain with a vector-network analyzer. The bounces indicate reflections or impedance discontinuities in the channel.