



Figure E Do-it-yourself  $Z_0$  Probe 2 has overshoot, again likely due to resistor/cable parasitic terms or incomplete coaxiality. At these speeds, don't do it yourself.

---