



(a)



(b)



(c)



(d)

Figure 2 Notable internal disparities magnify noticeable exterior differences among Access HD's DTA-1080D (a), Apex Digital's DT502 (b), Dish Network's TR-40 CRA (c), and Sansonic's FT-300A (d). Note that the excess thermal paste in the area surrounding the DT502's Realtek RTD2885 was the inadvertent result of my removal and replacement of the SoC's passive heatsink; the excess paste was not present when the CEGB originally came to me.