

Figure 2 A current transformer's iron core is susceptible to tampering with a large permanent magnet. When you place it next to the transformer, the magnet can saturate the core so that the sensing coil can't pick up the ac field in the power line (a). Rogowski coils have an advantage over current transformers because they employ air cores (b).

