

**TABLE 1— V_{SAFE} HYSTERESIS
OVER TEMPERATURE**

V_{SAFE}		0°C	25°C	50°C
On (V)	V_{IN} increasing	3.2	3.2	3.2
Off (V)	V_{IN} increasing	6.1	5.5	4.9
On (V)	V_{IN} decreasing	6	5.4	4.8
On (V)	V_{IN} decreasing	3.1	3.1	3.1