



Figure 2



Typical waveforms for driving a two-phase step motor include full-step, half-step, and microstepping.