



Figure 2

The frequency response of the two-pole filter in the circuit of Figure 1 shows a sharp roll-off between the corner frequency and approximately 10 times the corner frequency.