



**Figure 2**

The output spectrum of the power-line driver in Figure 1 shows that the worst-case empty-tone distortion is  $-35$  dBc.