

TABLE 1—WINDING DETAILS FOR TRANSFORMER

Start pin	End pin	Wire gauge	Turns	Inductance
2	1	26	21	28 mH
3	4	26	21	28 mH
6	10	38	380	17 mH

Core: EE25/13/7