

TABLE 1 INTEL P30 EMBEDDED-MEMORY
VOLTAGE-REGULATOR ERROR BUDGET

Parameter	Limits
Intel-specified supply limits	$1.8V \pm 0.1V$
LTC1844-regulator initial accuracy	$\pm 1.75\%$ (± 31.5 mV)
Dynamic-error allowance	± 68.5 mV