



Figure 2 In Figure 1, one of IC₁'s two audio outputs (Trace 1) has protection when its external terminal accidentally contacts an 18V supply voltage (Trace 2).