



Figure 1 This family of curves shows that a thermoelectric cooler may actually heat rather than cool at the maximum drive current if the heat sink the cooler is mounted on is less than perfect.